

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-021941**Date Inspected:** 01-Mar-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** ShangHai, China**CWI Name:** Sha Zhi**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

Summary of Items Observed: On this date Caltrans OSM Quality Assurance(QA) Inspector, DJ Shin was present during the times noted above for observations relative to the work being performed.

Bay 14

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is identified as Zhu Lin.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specifications (WPS). Listed below are the locations that were identified by this QA inspector.

Components: 13AW

PCMK: SEG3013D-232

Welder: 045143

WPS-B-T-2232-ESAB

PCMK: SEG3013B-255

Welder: 045221

WPS-B-T-2232-ESAB

PCMK: SEG3013E-226

Welder: 069469, 203871

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

WPS-B-T-2232-ESAB

PCMK: SEG3013P-061

Welder: 068445

WPS-B-T-2232-ESAB

PCMK: SEG3013R-026

Welder: 066421

WPS-B-T-2233-ESAB

Components: 14W

PCMK: SEG3020L-075

Welder: 045175

WPS-B-T-2232-ESAB

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Shield Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Zhu Lin.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector

Components: 13AW

PCMK: SEG3013F-048

Welder: 066038

WPS-B-P-2214-B-U3b

PCMK: SEG3013F-040

Welder: 067864

WPS-B-P-2212-B-U3b

PCMK: SEG3013K-039

Welder: 067764

WPS-B-P-2212-B-U3b

PCMK: SEG3013H-038

Welder: 067864

WPS-B-P-2212-B-U3b

PCMK: SEG3013K-047

Welder: 067764

WPS-B-P-2212-B-U3b

Components: 14W

PCMK: FB3316-001-011

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Welder: 067609

WPS-B-P-2214-FCM

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No relevant conversations

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Shin,DJ	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer
